

RECEIVED

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

APR 19 2010

Form C-141  
Revised October 10, 2003

HOBBSON  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company: Energen Resources Corp.	Contact: Andrew Cobb
Address: 3300 North A St. Bldg. 4, Ste. 100, Midland 79705	Telephone No.: 432-687-1155
Facility Name: West Lovington Strawn Unit #11	Facility Type: Oil and Gas Production Facility

Surface Owner: Dan Field	Mineral Owner: Energen Resources	Lease No.: 277820
--------------------------	----------------------------------	-------------------

LOCATION OF RELEASE

API 30.025.32852

Unit Letter B	Section: 33	Township: 15S	Range 35E	Feet from the 760	North/South Line N	Feet from the 2090	East/West Line E	County: Lea
------------------	----------------	------------------	--------------	----------------------	-----------------------	-----------------------	---------------------	-------------

Latitude 32-58-44.00 Longitude 103-24-50.00

WTR SS

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 barrels	Volume Recovered: 15 barrels
Source of Release: SWD Transfer Pump	Date and Hour of Occurrence: 11-10-09 @ unknown	Date and Hour of Discovery: 11-10-09 @ 10:30 am

Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?
--	------------------

By Whom?	Date and Hour
----------	---------------

Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
---	---

If a Watercourse was impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A 1/2" stainless steel plug failed on a salt water disposal pump this facility. The pump was located within the spill containment walls of the battery but a volume of approximately 30 barrels was spilled outside the containment.

Describe Area Affected and Cleanup Action Taken.\*  
The chloride area outside the battery containment was dug out and will be replaced with soil purchased from the surface owner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Andrew Cobb</i>	<b>OIL CONSERVATION DIVISION</b> <i>[Signature]</i>	
Printed Name: Andrew Cobb	Approved by District Supervisor <b>ENVIRONMENTAL ENGINEER</b>	
Title: Sr. Safety & Environmental Specialist	Approval Date: 4.19.10	Expiration Date: 6.18.10
E-mail Address: andy.cobb@energen.com	Conditions of Approval: <input checked="" type="checkbox"/> Attached <input type="checkbox"/>	
Date: 12-4-09 Phone: 432-686-3599	SUBMIT FINAL C.A.I w/DOCS BY IRP # 10.4.2482	

\* Attach Additional Sheets If Necessary