

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 23 2010
HOBBSCOCD

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Southern Union Gas Services	Contact: Rose Slade
Address P.O. Box 1226 Jal, N.M. 88252	Telephone No. 432-940-5147
Facility Name: Lea County Field Dept.	Facility Type: 6" lateral
Surface Owner: Gerald Doom	Mineral Owner
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	26	24	37					Lea County

Latitude_32 11.384 Longitude_103 08.154

NATURE OF RELEASE API # 30-025-38822-00-00

Type of Release: crude oil/produced water	Volume of Release: 5 barrels	Volume Recovered: 0
Source of Release: 6" pipeline	Date and Hour of Occurrence: 4/19/2010 at 11:30 pm (not reportable at the time)	Date and Hour of Discovery: 4/20/2010 At 7:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeoffery Lecking (OCD)	
By Whom? Rose Slade	Date and Hour: 4/20/2010 at 8:58 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		

WATER @ 700'

Describe Cause of Problem and Remedial Action Taken.*

The line had a split on the 6" steel line. They had to replace with 100 feet of poly pipe. EHS was notified and I immediately dispatched my environmental company to go to the site and remediate the site.

Describe Area Affected and Cleanup Action Taken.*

Approximately 3' x 25' of land was affected by the leak. The environmental consultant delineated & sampled the site affected and put the contaminated soil onto plastic until the analytical comes back with analysis for closure. The landowner was notified immediately by SUGS personnel. SUGS will be working closely with the NMOCD and the landowner to reach closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rosa L. Slade</i>	OIL CONSERVATION DIVISION	
Printed Name: Rosa L. Slade	Approved by ENV ENGINEER: District Supervisor: <i>Jeoffery Lecking</i>	
Title: EHS Compliance Specialist	Approval Date: 04/26/10	Expiration Date: 06/28/10
E-mail Address: rose.slade@sug.com	Conditions of Approval: SUBMIT FINAL C-141 BY 06/28/10	Attached <input type="checkbox"/>
Date: 4/23/2010	Phone: 432-940-5147	IRP-10-4-2488

* Attach Additional Sheets If Necessary