

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 20 2010
HOBBS, NM

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	SandRidge Energy	Contact	Ron Ragland
Address	3504 NW County Road Hobbs, N.M.	Telephone No.	(575) 392-9797
Facility Name	MGBU # 77	Facility Type	Pumping Well

Surface Owner	Federal BLM	Mineral Owner		Lease No.	30-025-00562
---------------	-------------	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	15	17S	32E	2310	North	660	East	Lea

Latitude 32.86503 Longitude -103.74295

NATURE OF RELEASE

Type of Release	Oil/Water	Volume of Release	20 bbls.	Volume Recovered	15 bbls.
Source of Release	Flowline	Date and Hour of Occurrence	3/18/10 9:00 a.m.	Date and Hour of Discovery	3/18/2010 10:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Andrea Massengill BLM/OCD		
By Whom?	Adan Ornelas	Date and Hour	3/18/2010 2:42 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

WATER @ 60'

Describe Cause of Problem and Remedial Action Taken.*

Fused flowline came apart Repaired line

Describe Area Affected and Cleanup Action Taken.*

Off site land impacted puddling approx. 1050' of native vegetation. Cleaned area with vac. truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ron Ragland by Mary Jo Turner</i>	OIL CONSERVATION DIVISION	
Printed Name: Ron Ragland	Approved by ENV ENGINEER : District Supervisor: <i>Stephany Lakin</i>	
Title: Sr. Prod. Foreman	Approval Date: <i>04/30/10</i>	Expiration Date: <i>06/30/16</i>
E-mail Address: rragland@sdrge.com	Conditions of Approval: SUBMIT WORKPLAN FOR INVESTIGATION. INVESTIGATION SHOULD DELINEATE HORIZONTAL	Attached <input type="checkbox"/>
Date: March 18, 2010 Phone: (575) 392-9797	AND VERTICAL EXTENT OF CONTAMINATION. DELINEATE TO CLEAN + I. SUBMIT FINAL C-141 BY <i>06/30/2010</i>	<i>RRP-10-4-2500</i>

* Attach Additional Sheets If Necessary



energy to go further

FAX MEMO

Date:

Number of pages including cover sheet:

To:

Geoffrey Leking

Phone: 575.393.6161

Fax: 575.393.0720

CC:

From:

MAIL: Mary Jo Turner

DELIVERY:

Phone: 575.392-9797

Fax: 575.392.8971

E-Mail:

REMARKS: Urgent For your review Reply ASAP Please comment

CC: BLM & OCD – Hobbs Office

CONFIDENTIALITY NOTICE

This facsimile transmission (and documents accompanying it) may contain confidential information belonging to the sender. The information is intended for the use of the individual or entity to whom this transmission is addressed. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, or the taking of any action in reliance on the contents of this information is strictly prohibited. If you have received this transmission in error, please immediately notify us by telephone to arrange the return of the documents. Thank you.



ENVIRONMENTAL EVENT FORM (New Mexico)

19-Mar-2010

SandRidge Energy, Inc.
123 Robert S. Kerr Ave.
Oklahoma City, OK 73102
Attn: Mike Hamilton, Env. Mgr.

Event(s)	<input checked="" type="checkbox"/> Spill/Release to Land or Water	<input type="checkbox"/> Scheduled/Planned Maint?	<input type="checkbox"/> Malfunction?
	<input type="checkbox"/> Excess Air Emission Event	<input type="checkbox"/> Offshore Event?	<input type="checkbox"/> Start-up/Shut-down?
	<input type="checkbox"/> Non-Compliance/Deviation Event	<input type="checkbox"/> NPDES Discharge Event?	<input type="checkbox"/> Complaint?

Material(s)	MATERIAL(S):	Produced Oil	Produced Water
	TOTAL AMOUNT RELEASED:	Bbls To Land	15 Bbls To Land
	TOTAL AMOUNT RECOVERED:	6	10
	PHYSICAL OBSERVATIONS:	Color = Black	Odor = Sulfur
	LIMIT/REPORTABLE QTY:	25 Bbls	By: Adan Ornelas

Release Location	SITE/LEASE/LOCATION:	Maljamar Grayburg Unit	RN #	Permit	
	OWNER/OPERATOR:	SandRidge Energy, Inc	CN #	RRC #	
	SOURCE:	Well 77	EQUIPMENT:	Flow Line	EPN #
	SOURCE / EQUIP. DESCRIPTION:	Fused flowline came apart			
	WEATHER CONDITIONS:	Cloudy	Temp	70	F Wind 5 mph from the N
	LEGAL (OR DIRECTIONS):	2310' FNL & 660' FEL Sec. 16 T17S R37E			County: Lea
	COORDINATES:	LATITUDE:	LONGITUDE:		

Impacts	CONTAINMENT:	All (100%) retained within secondary containment structure	lined	<input checked="" type="checkbox"/> unlined
	OFF-SITE LAND IMPACTED:	Puddling covering approximately 1,050 ft ² of Native Vegetation		
	OFF-SITE WATER IMPACTED:	covering approximately 0 ft ² of N/A		
	OTHER:	Injures (on-site)	Injures (off-site)	Evacuation

When	STARTED:	Date (mm/dd/yy): 3/18/2010	Time: 9:00
	STOPPED:	Date (mm/dd/yy): 3/18/2010	Time: 10:00
	DURATION:	0 Day(s), 1.00 Hours	Discovered By: Adan Ornelas

Cause(s)	<input type="checkbox"/> Internal Corrosion	<input type="checkbox"/> Loss of Electrical Power Supply	<input type="checkbox"/> Overtime Labor / 3rd Party
	<input type="checkbox"/> External Corrosion	<input type="checkbox"/> Loss of Instrument Air / Feed Stream	<input type="checkbox"/> External Impact
	<input checked="" type="checkbox"/> Mechanical Failure	<input type="checkbox"/> Design / Construction	<input type="checkbox"/> Act Of God
	<input type="checkbox"/> Improper Operation	<input type="checkbox"/> Insufficient Maintenance	<input type="checkbox"/> Other

Response(s)	<input checked="" type="checkbox"/> Facility Shut-down	<input type="checkbox"/> Absorbent Materials Applied	<input type="checkbox"/> Stockpiled & Covered Impacted Soil
	<input type="checkbox"/> Equipment Blocked-In	<input type="checkbox"/> Flushed with Water	<input type="checkbox"/> Removed & Disposed Impacted Soil
	<input type="checkbox"/> Material Transferred from Damaged Equipment	<input type="checkbox"/> Flare	<input type="checkbox"/> Treated Impacted Soils In-place
	<input type="checkbox"/> Temporary Containment Installed	<input type="checkbox"/> Collect & Transferred Free Liquids	<input type="checkbox"/> Other

CALLS MADE BY: Ron Ragland						
Agency/Entity	Contact Number:	Name of Person Contacted	Date (mm/dd/yy)	Time	Case #	
National Resp Center (NRC)	(800) 424-8802	Dwight Phillips	3/19/10	9:18 AM		
New Mexico OCD (Division)	(505) 476-3440					
New Mexico OCD (District)						
Bureau Of Land Management	(576) 393-3612	Andrea Massengill	3/18/10	2:43 PM		
Co. LEPC						
SandRidge EHS	(432) 967-5870		3/19/10	9:28 AM		
Landman/Prop Owner						
MMS District						

For Additional Information, Contact: Ron Ragland at (432) 290-6404 Report Date: 3/19/2010