

District I
1625 N French Dr, Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87411
District IV
2040 South Pacheco, Santa Fe, NM 87505

RECEIVED

MAY 04 2010

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Co. L.P.	Contact Tracy Kidd
Address P.O. Box 250, Artesia, NM 88210	Telephone No. 575-513-0628
Facility Name Tomcat 21 Battery	Facility Type Battery

Surface Owner Federal	Mineral Owner	Lease No. NM-86153
-----------------------	---------------	--------------------

LOCATION OF RELEASE

API # 30.025.33653 H 23.23.32
DIAMOND TAIL FED # 2 SWD BATTERY

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	21	23S	32E	1980	North	1980	West	Lea

NATURE OF RELEASE

Type of Release Produced water	170,000 PPM CHLORIDE	Volume of Release 100 bbls	Volume Recovered 0
Source of Release Poly pipe line		Date and Hour of Occurrence 3/31/10 11:00 AM	Date and Hour of Discovery 3/31/2010 11:00AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson OCD	
By Whom? Tracy Kidd		Date and Hour 3/31/10 3:00 PM	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

n/a

Describe Cause of Problem and Remedial Action Taken.*

Three inch SDR 7 poly line parted in fused section of pipe releasing an estimated 100 bbls of water. Line was repaired and soil samples were taken.

Describe Area Affected and Cleanup Action Taken.*

The affected area was 500' long and 2' to 60' in width. Whole-Earth has been called to do remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: <i>Tracy A. Kidd</i>	OIL CONSERVATION DIVISION <i>L. Johnson</i>	
Printed Name: Tracy Kidd	Approved by <input type="checkbox"/> District ENVIRONMENTAL ENGINEER	
Title: Production Foreman	Approval Date: 5.6.10	Expiration Date: 7.6.10
Date: 4/5/2010 Phone: 575-513-0628	Conditions of Approval: SUBMIT FINAL C-141 Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

W/DCS BY IRP# 10.5.2509