

RECEIVED APR 23 2010

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-25699
MLB1011352696

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company ConocoPhillips Company 217817	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name James A Battery	Facility Type Oil

Surface Owner NMOCD	Mineral Owner BLM	Lease No. 3001525699
---------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	02	22S	30E	1652	South	1980	East	Eddy

Latitude N32 25.112' Longitude W103 50.857'

NATURE OF RELEASE



Type of Release Produced Water	Volume of Release 12 BBL	Volume Recovered 0 BBL
Source of Release 3" steel line connection adapter	Date and Hour of Occurrence 4/22/10	Date and Hour of Discovery 4/22/10
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Jesse Sosa	Date and Hour 4/22/10 2:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid.

Describe Area Affected and Cleanup Action Taken.*
Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be remediated in place. NMOCD was notified. Soil to be hauled off and replaced. Soil samples will be taken to verify clean up and sent to NMOCD (Mike Bratcher) for finalization.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Signed By  Approved by District Supervisor	
Title: HSER Lead	Approval Date: APR 23 2010	Expiration Date:
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval: REMEDIATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 5/23/10	Attached <input type="checkbox"/>
Date: 04/22/2010	Phone: (505)391-3126	

* Attach Additional Sheets If Necessary

MLB1011353322