

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Chevron Dollarhide	Contact Ricky Heredia
Address Drawer 29 Andrews Texas 19714	Telephone No. 432-523-3655 ext. 7603
Facility Name WDDU Injection System	Facility Type Injection System

Surface Owner George Willis	Mineral Owner Chevron	Lease No.
-----------------------------	-----------------------	-----------

LOCATION OF RELEASE NEARBY WELL WDDU # 1
API # 30-025-32162-00-00

Unit Letter J	Section 32	Township 24 S	Range 38 E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea County New Mexico
---------------	------------	---------------	------------	---------------	------------------	---------------	----------------	------------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Volume of Release 19.85 PW	Volume Recovered 0
Source of Release	Date and Hour of Occurrence 4/25/2010 6:30pm	Date and Hour of Discovery 4/25/2010 6:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 34'

Describe Cause of Problem and Remedial Action Taken.*
High Pressure line glued fitting came unglued causing spill 19.85 bbls Produce Water
Leak detection shut pump down minimizing spill

Describe Area Affected and Cleanup Action Taken.*
Free liquids were removed from the spill area. The impacted area will be evaluated for depth and quantity of chlorides. If additional remediation is needed a work plan will submitted to the NM ODD describing the proposed actions to be taken.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name:	Approved by District Supervisor ENV ENGINEER: <i>Jeffrey Lebing</i>	
Title: Dollarhide Field HES	Approval Date: 05/12/10	Expiration Date: 07/10/12
E-mail Address: rhrc@chevron.com	Conditions of Approval: SUBMIT FINAL C-141 BY 07/12/10	Attached <input type="checkbox"/> IRP-10-5-2523
Date: 4/29/2010 Phone: 432-238-2343		

* Attach Additional Sheets If Necessary