

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88213
District III
1000 Rio Brazos Road, Aztec, NM 87001
District IV
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED
DEC 10 2009
HOBBSUCD

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company BP America Production Co.	Contact Steve Pacheco
Address P.O. Box 1089, Eunice, NM 88231	Telephone No. 505.394.1600 / 575-677-3642 EXT. 210
Facility Name McDonald WN State # 36	Facility Type Oil and Water Facility

Surface Owner State	Mineral Owner State	Lease No. API # 3002535416
---------------------	---------------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	15	22S	36E	1980	S	1980	E	Lea

NATURE OF RELEASE

Type of Release Produced Water / OIL	Volume of Release 8.4 bbl oil 32.4 bbl water	Volume Recovered 8 bbl oil 32 bbl water
Source of Release BROKEN LOAD LINE FROM TANK	Date and Hour of Occurrence 12.7.09 approx 8:50 AM	Date and Hour of Discovery 12.7.09 8:50 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD, HOBBS, NM	
By Whom? Steve Pacheco	Date and Hour 12.7.09 11:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*
A 4" X 3" swedge between the tank and block valve broke possibly due to cold temperatures resulting in tank liquid draining.

Describe Area Affected and Cleanup Action Taken.*
Drain and replace bad piping and fittings. Remove contaminated soil and haul to appropriate land fill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Steve Pacheco</i>	OIL CONSERVATION DIVISION	
	Approved by ENV ENGINEER: District Supervisor: <i>[Signature]</i>	
Printed Name: Steve Pacheco	Approval Date: 05/17/10	Expiration Date: 07/17/10
Title: Operations Specialist & (Team Leader Relief for SENM area)	Attached <input type="checkbox"/> IRP-10-5-2528	

Date: 12.7.09 Phone: 505.394.1600 / 575-677-3642

Conditions of Approval: DELINEATE CONTAMINATION HORIZONTALLY AND VERTICALLY TO CLEAN +1. SUBMIT FINAL C-141 BY 07/17/10.

* Attach Additional Sheets If Necessary EXT. 210