

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
Revised October 10, 2003

APR 09 2010
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
HOBBSOCD

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 575.394.2534, Chuck Tolsma 575.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (575) 394-2534
Facility Name: Eunice Gas Plant	Facility Type: Natural Gas Gathering System
Surface Owner: J. D. Martin	Mineral Owner:
	Lease No.

LOCATION OF RELEASE

30.025, 21497

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	22	22	37					Lea

Latitude 32.38078N Longitude 103.15832

NATURE OF RELEASE

Type of Release: Natural Gas and liquid from a 20 inch gathering line with 12 psi flowing 3MMCFD.	Volume of Release Approximately 6 Barrels of liquid and 210 mcf of natural gas by calculation.	Volume Recovered: NONE
Source of Release: Natural gas 20 inch gathering line with a 1 inch hole from external corrosion.	Date and Hour of Occurrence: 7 AM February 12, 2010	Date and Hour of Discovery 10 AM February 12, 2010
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson OCD in Hobbs by phone and to OCD on call phone	
By Whom? Roger Holland	Date and Hour 11AM February 12, 2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

20 inch natural gas gathering line developed a 1 inch hole from corrosion. Line was excavated and leak repaired. Contaminated soil will be excavated and disposed of in an OCD approved landfill

Describe Area Affected and Cleanup Action Taken.*

The area affected will be excavated and soil contamination disposed of. Area will be cleaned and sampled to insure compliance with OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION <i>L Johnson</i>	
Printed Name: Don Embrey	Approved by District ENVIRONMENTAL ENGINEER	
Title: Training Specialist	Approval Date: 4.9.10	Expiration Date: 6.9.10
E-mail Address: dembrey@targaresources.com	Conditions of Approval.	
Date: February 17, 2010 Phone: (432) 688-0546	Attached <input type="checkbox"/>	

SUBMITTING C-141 w/Docs BY (RP) # 104-2473

* Attach Additional Sheets If Necessary