

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JUN 08 2010
HOBSOCD

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Targa Midstream Services, L.P.	Contact: Ralph England
Address: P.O. Box 1689	Telephone No: 575.441.4653
Facility Name: Saunders Plant	Facility Type: Gas Manufacturing Plant
Surface Owner: G. E. Peterson	Mineral Owner
Lease No.: N/A	

LOCATION OF RELEASE

API 30.025.01195 (SAUNDERS)
(SWD)

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	19	5S	32E					Roosevelt

Latitude 33.86202 Longitude 103.51649

NATURE OF RELEASE

Type of Release: Natural gas and liquids from a 6" steel gathering line.	Volume of Release: Approximately 5 bbls. unknown amount of natural gas	Volume Recovered Approximately 4 bbls.
Source of Release: 6" natural gas gathering line with a 1/2" hole, 10# pressure, and zero flow	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 6/4/2010 - 2:30 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken *

A pipeline leak was discovered in the North Peterson field that released approximately 5 bbls. of oil. The leak was isolated and repaired; a vacuum truck was used to recover fluid.

Describe Area Affected and Cleanup Action Taken.*

Affected area was contained within our pipeline right of way Vacuum truck was used to recover fluid. Contaminated soil will be removed and taken to an OCD approved land farm. Area will be cleaned and sampled to ensure compliance with the OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform connective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ralph England</i>	<u>OIL CONSERVATION DIVISION</u> <i>[Signature]</i>	
Printed Name: Ralph England	Approved by District <u>ENVIRONMENTAL ENGINEER</u>	
Title: Field Supervisor	Approval Date: <u>6.8.10</u>	Expiration Date: <u>8.9.10</u>
E-mail Address: REngland@targaresources.com	Conditions of Approval: Attached <input type="checkbox"/>	
Date: June 7, 2010 Phone: 575.441.4653	SUBMIT FINAC C-141 w/DOCS BY <u>IRP# 10.6.2548</u>	

* Attach Additional Sheets If Necessary

INC N LWT 1015928303

ADM PLUS 1015928835