

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUN 08 2010

HOBBS

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>Rice Operating</b>	Contact <b>Hack Conder</b>
Address <b>122 W. Taylor St., Hobbs, NM 88240</b>	Telephone No. <b>(575) 393-9174</b>
Facility Name <b>J-6 EOL</b>	Facility Type <b>Salt Water Gathering System</b>
Surface Owner <b>STATE/ JAMES T. FOLEY</b>	Mineral Owner
Lease No. <b>30-025-12800</b> API Number 30-025-12800	

**LOCATION OF RELEASE**

Unit Letter <b>J</b>	Section <b>6</b>	Township <b>19S</b>	Range <b>37E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>LEA</b>
----------------------	------------------	---------------------	------------------	---------------	------------------	---------------	----------------	-------------------

Latitude: 32°41'21.5" Longitude 103°17'19.8" (NAD 83)

WTR 45'

**NATURE OF RELEASE**

Type of Release : <b>PRODUCED WATER</b>	Volume of Release <b>70</b>	Volume Recovered <b>60</b>
Source of Release : <b>EOL BOX</b>	Date and Hour of Occurrence <b>6/6/2010</b>	Date and Hour of Discovery <b>6/6/2010 8:55 AM</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Message left with Larry Johnson, NMOCD</b>	
By Whom? <b>Hack Conder</b>	Date and Hour <b>6/7/2010, 2:00 PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
**A connection in the J-6 EOL box broke causing the box to fill and overflow. A vacuum truck was dispatched immediately to remove and properly dispose of the released water. The connection was permanently repaired.**

Describe Area Affected and Cleanup Action Taken.\*  
**12,400 sq ft of pasture/access road was affected. One-call submitted 6/7/2010 to begin scrapping.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Hack Conder</b>	Approved by District <b>ENVIRONMENTAL ENGINEER</b>	
Title: <b>Environmental Manager</b>	Approval Date: <b>6.8.10</b>	Expiration Date: <b>8.9.10</b>
E-mail Address: <b>hconder@riceswd.com</b>	Conditions of Approval:	
Date: <b>6/7/2010</b> Phone: <b>(575) 393-9174</b>	Attached <input type="checkbox"/> IRP# <b>10-6-2051</b>	


\* Attach Additional Sheets If Necessary

WCI nLW 101593 3599  
A?? P625 101593 9366

SUBMIT FINAL C-141 w/ Decs BY

N

EME JCT J-6 EB- 15/37



1496'  
6237'  
4600  

---

12,333