

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JUN -4 2010
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-29291

Release Notification and Corrective Action

NMLB 1016045970

OPERATOR

Initial Report

Final Report

Name of Company Devon Energy 6137	Contact Jerry Matthews, Foreman
Address 6488 Seven Rivers Hwy – P.O. Box 250	Telephone No. 575-748-5234
Facility Name Ore Ida 14 Federal #12	Facility Type

Surface Owner BLM	Mineral Owner	Lease No.
--------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	24S	29E	1880	FSL	2480	FWL	Eddy

Latitude - **N 32.21516** * Longitude - **103.94927**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15 bbls	Volume Recovered 0
Source of Release Flowline	Date and Hour of Occurrence 05/27/10 – 11:30 am	Date and Hour of Discovery 05-27-10 – 11:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos	
By Whom? Eric Bell, Lease Operator	Date and Hour 05-27-10 – 3:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On arrival at the Ore Ida 14 #12 the Lease Operator observed some guys doing some dirt work near our poly line; also observed standing water. Went to investigate where it was coming from and an employee from B&H informed Lease Operator that they discovered the leak and went into town to get a clamp and they tried clamping the line. Called and had gang come out and fix line

Describe Area Affected and Cleanup Action Taken.*

Took clamp off and repaired line and will teal, rake, and fertilize affective area on location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Mykol Horner	OIL CONSERVATION DIVISION	
Printed Name: Mykol Horner	Approved by District Supervisor Signed By: <i>[Signature]</i>	
Title: Field Tech 1	Approval Date: JUN 09 2010	Expiration Date:
E-mail Address: mykol.horner@dvn.com	Conditions of Approval: REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: June 30, 2010	Attached <input type="checkbox"/>
Date:	Phone: 575-748-0160	

* Attach Additional Sheets If Necessary

PMLB 1016046346

2RP-417