

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**RECEIVED**

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUL 14 2010  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**HOBBSOCD**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Southern Union Gas Services	Contact	Rose Slade
Address	P.O. Box 1226 Jal, New Mexico 88252	Telephone No.	432-940-5147
Facility Name	Wantz Compressor Station	Facility Type	Natural Gas Compressor Station
Surface Owner	Mary Wantz	Mineral Owner	
		Lease No.	30-025-38822

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	21	21S	37E					Lea

Latitude 32.460176 Longitude 103.175548

WTR 80

**NATURE OF RELEASE**

Type of Release	Crude Oil and Produced Water	Volume of Release	10 BBLs	Volume Recovered	2 BBLs
Source of Release	Truck Release	Date and Hour of Occurrence	July 7, 2010, 1650 hrs	Date and Hour of Discovery	July 7, 2010, 1650 hrs
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

WTR 20'

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A hose on a 3<sup>rd</sup> party transport truck failed during loading operations, releasing a mixture of crude oil and produced water. A vacuum truck was used to recover free fluids

Describe Area Affected and Cleanup Action Taken.\*

An area measuring approximately 1,500 square feet was affected by the release. Clean sorb was applied to the surface stain to further stabilize the release and absorbent booms were installed in low areas along the fenceline to minimize the potential for travel outside the station during a rain event. The release will be remediated according to NMOCD regulatory guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rose L. Slade</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rose L. Slade	<i>Johnson</i> Approved by District Supervisor	
Title: EHS Compliance Specialist	Approval Date: 7.13.10	Expiration Date: 9.13.10
E-mail Address: rose.slade@sug.com	Conditions of Approval	
Date: 7/9/2010 Phone: 432-940-5147	Attached <input type="checkbox"/>	
SUBMIT FINAL C-141 w/DOCS BA (RP# 10-7-2580)		

\* Attach Additional Sheets If Necessary

n lwt 101 942 9623

PLWT 101 9430032

PPP