

RECEIVED

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 14 2010

HOBBSOCD

Form C- 41
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <u>Fasken Oil and Ranch, Ltd.</u>	Contact <u>Jimmy D. Carlile</u>
Address <u>303 W. Wall St., Ste. 1800, Midland</u>	Telephone No. <u>432-687-1777</u>
Facility Name <u>Denton No. 10</u>	Facility Type <u>Oil Well</u>

Surface Owner <u>Darr Angell</u>	Mineral Owner	Lease No.
----------------------------------	---------------	-----------

LOCATION OF RELEASE

30-025-05297

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>H</u>	<u>11</u>	<u>15S</u>	<u>37E</u>	<u>1982'</u>	<u>North</u>	<u>562'</u>	<u>East</u>	<u>Lea</u>

API No. 30-025-05297

Latitude _____ Longitude _____

WTR 92'

NATURE OF RELEASE

Type of Release <u>Oil and produced water</u>	Volume of Release <u>28</u>	Volume Recovered <u>22</u>
Source of Release <u>Flowline</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>7-5-10</u> <u>8:00 am</u>	<u>7-5-10</u> <u>9:00 am</u>
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <u>N/A</u>	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

External corrosion on flowline. Section of pipe replaced.

Describe Area Affected and Cleanup Action Taken.*

215' X 115' leak occurred in area of standing rain water. Vacuum trucks picked up all water and oil. Will allow area to dry and grab soil samples to check for chloride levels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jimmy D. Carlile</u>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: <u>Jimmy D. Carlile</u>	<u>ENVIRONMENTAL ENGINEER</u>	
Title: <u>Regulatory Affairs Coordinator</u>	Approval Date: <u>7-14-10</u>	Expiration Date: <u>9-14-10</u>
E-mail Address: <u>jimmyc@forl.com</u>	Conditions of Approval:	
Date: <u>7-12-10</u> Phone: <u>432-687-1777</u>	<u>Submitted Final C-141 w/Docs by IRP# 10-7-2583</u>	

* Attach Additional Sheets If Necessary

n LWS 1019530957
PLWS 1019534610