

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Name of Company	Southern Union Gas Services	Contact	Rose Slade
Address	P.O. Box 1226 Jal, New Mexico 88252	Telephone No.	432-940-5147
Facility Name	Line 2B Release	Facility Type	Natural Gas Pipeline
Surface Owner	Woolworth Estate	Mineral Owner	
		Lease No.	30-025-38823

LOCATION OF RELEASE

38822

Unit Letter "O"	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
	31	24S	37E					

Latitude N 32 degrees 01.212' Longitude W 103 degrees 11.978'

WTR-250'

NATURE OF RELEASE

Type of Release	Crude Oil and Produced Water	Volume of Release	8 BBLS	Volume Recovered	5 BBLS
Source of Release	6-Inch Steel Pipeline	Date and Hour of Occurrence	July 14, 2010, 1100 hrs	Date and Hour of Discovery	July 14, 2010, 1100 hrs
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson, NMOCD Hobbs District Office		
By Whom?	Curt Stanley	Date and Hour	July 15, 2010, 0920 hrs		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
During pipeline change-out activities, crude oil and produced water were released into a pipeline trench. A vacuum truck recovered free fluids and an onsite backhoe was used to immediately excavate the saturated soil, stockpiling the impacted soil adjacent to the pipeline trench.

Describe Area Affected and Cleanup Action Taken.*
A pipeline trench measuring approximately 60 linear feet was affected by the release. During initial response activities saturated soil was excavated and the area of impact was delineated. Soil samples will be collected and submitted to the laboratory to evaluate the need for additional remediation activities. The release will be remediated per NMOCD regulatory guidelines

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Rosa L. Slade</i>	OIL CONSERVATION DIVISION	
Printed Name:	Rosa L. Slade	<i>L. Johnson</i> Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title:	EHS Compliance Specialist	Approval Date:	7.16.10
E-mail Address:	rose.slade@sug.com	Expiration Date:	8.16.10
Date:	7/15/2010	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-940-5147	SUBMIT FINAL C-141 w/Docs BY 10.7-2586	

* Attach Additional Sheets If Necessary

n LWS 1019732835
PLWJ 1019733289