

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Agua Sucia, LLC	Contact	Louis Edgett / Ben Stone, Agent, SOS Consulting, LLC
Address	14605 Memorial Dr, Bixby, OK 74008	Telephone No.	(575) 631-3387 / (903) 488-9850
Facility Name	Government 'E' No.1 SWD Facility	Facility Type	Salt Water Disposal Facility

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	
---------------	-----	---------------	-----	-----------	--

LOCATION OF RELEASE API# -30-025-23708-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	25	19-S	34-E	610'	FSL	1880'	West	Lea

Latitude 32.625818 Longitude -103.516315

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	<5 bbl	Volume Recovered	90%
Source of Release	Tank Overfilled by truck driver during routine off-loading of produced water.	Date and Hour Occurred Between	5/23 7:00 pm and 5/24 8:00 am	Date and Hour of Discovery	5/24/10 8:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



WATER @ 90'

Describe Cause of Problem and Remedial Action Taken.* Truck driver did not stop off-loading produced water load in time. Transporters and trucking companies notified to pay attention while using these facilities.

Describe Area Affected and Cleanup Action Taken.*

Overflow is contained to bermed area surface and subgrade soils. Spill is being scooped and placed on plastic liner for drying and will be disposed of at approved CRI facility. Replaced with fresh dirt. Dirt volume is less than 5 cubic yards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Ben Stone	Approved by ENV ENGINEER:	
Title:	Agent, SOS Consulting, LLC	Approval Date:	07/19/10
E-mail Address:	ben@sosconsulting.us	Expiration Date:	09/20/10
Date:	05/24/10	Phone:	(903) 488-9850
		Conditions of Approval:	SUBMIT FINAL C-141 BY 09/20/10
		Attached	<input type="checkbox"/>
		WRP-10-7-2589	

* Attach Additional Sheets If Necessary