

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Rec'd NMOCD  
6/5/09

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

MLB 10223 56827

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	- RJ Unit #119	Facility Type	- Injection Well
Surface Owner	Mineral Owner	Lease No. 30-015-03146	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	27	17S	29E	660	South	1980	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**



Type of Release-Produced Water	Volume of Release-200bbbs	Volume Recovered- 150bbbs
Source of Release- Hole in 2" injection line	Date and Hour of Occurrence- 5/30/09- 12:00 pm	Date and Hour of Discovery 5/30/09-12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD District 2	
By Whom? Kent Greenway	Date and Hour 6/1/09- 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Hole in a 2" steel injection line. Injection was shut in at this location and the line will be replaced

Describe Area Affected and Cleanup Action Taken.\*  
Approximately 50' X 100' area in pasture was affected. All liquid was vacuumed up. The area is being dug out to a 1' depth for testing. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kanicia Carrillo	Approved by  District Supervisor	
Title: Regulatory Analyst	Approval Date: <b>AUG 11 2010</b>	Expiration Date:
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/3/09 Phone: 432-685-4332	REMEDATION per OCD Rules and Guidelines. <b>SUBMIT REMEDIATION PROPOSAL BY: PROPOSAL REC'D</b>	

\* Attach Additional Sheets If Necessary

MLB 10223 57148  
p MLB 10223 57385

2RP-426