

REC'D VIA EMAIL 11/11/09

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

MLB10223.57667

#### OPERATOR

Initial Report  Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 100 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	RJ Unit 110	Facility Type	Injection Line

Surface Owner	Federal	Mineral Owner		Lease No.	30-015-03152
---------------	---------	---------------	--	-----------	--------------

#### LOCATION OF RELEASE

\*\*\* Across from the RJ Unit #121 (API# 30-015-03142)

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	17S	29E	660	South	660	East	Eddy

Latitude N32' 48.00 Longitude W104' 03.402

#### NATURE OF RELEASE


Type of Release- Produced water	Volume of Release-100bbls	Volume Recovered- 400 bbls prod wtr & rain wtr
Source of Release- Injection Line	Date and Hour of Occurrence- 10/23/09	Date and Hour of Discovery 10/23/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston	
By Whom? Pat Ellis	Date and Hour 10/26/09 2:08pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Hole in injection line, line is shut in.

Describe Area Affected and Cleanup Action Taken.\*  
Spill occurred across the road from the RJ Unit #121 well, roughly 50x150 area.  
Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kanicia Carrillo	Approved by District Supervisor Signed By: 	
Title: Regulatory Analyst	Approval Date: <b>AUG 11 2010</b>	Expiration Date:
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/11/09 Phone: 432-685-4332	<b>REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: Proposal Dec 11</b>	

\* Attach Additional Sheets If Necessary

MLB1022358013  
p MLB1022358091

2 RP-427