

REC'D VIA EMAIL 11/11/09

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMB10223-59667

OPERATOR Initial Report Final Report

Name of Company COG OPERATING LLC <i>229/37</i>	Contact Kancia Carrillo
Address 550 W. Texas, Suite 100 Midland, TX 79701	Telephone No. 432-685-4332
Facility Name - RJ Unit 110	Facility Type- Injection Line

Surface Owner Federal	Mineral Owner	Lease No. 30-015-03152
------------------------------	---------------	-------------------------------

LOCATION OF RELEASE *** Across from the RJ Unit #121 (API# 30-015-03142)

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	17S	29E	660	South	660	East	Eddy

Latitude **N32' 48.00** Longitude **W104' 03.402**

NATURE OF RELEASE




Type of Release- Produced water	Volume of Release- 100bbbls	Volume Recovered- 400 bbls prod wtr & rain wtr
Source of Release- Injection Line	Date and Hour of Occurrence- 10/23/09	Date and Hour of Discovery 10/23/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston	
By Whom? Pat Ellis	Date and Hour 10/26/09 2 08pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken.*
Hole in injection line, line is shut in

Describe Area Affected and Cleanup Action Taken *
**Spill occurred across the road from the RJ Unit #121 well, roughly 50x150 area
Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature 	OIL CONSERVATION DIVISION	
Printed Name Kancia Carrillo	Approved by District Supervisor 	Signed By 
Title Regulatory Analyst	Approval Date AUG 11 2010	Expiration Date
E-mail Address kcarrillo@conchoresources.com	Conditions of Approval.	Attached <input type="checkbox"/>
Date 11/11/09 Phone 432-685-4332	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: <u>Proposal Dec's</u>	

* Attach Additional Sheets If Necessary

NMB1022358013
NMB1022358071

2 RP-427