

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
SEP 22 2010
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR X Initial Report Final Report

Name of Company Salty dog	Contact Jon Ammons
Address Po Box 513 Hobbs, NM	Telephone No. 575-393-8352
Facility Name Salty Dog	Facility Type B/W & F/W facility

Surface Owner Snyder ranches	Mineral Owner Salty dog inc.	Lease No.
------------------------------	------------------------------	-----------

LOCATION OF RELEASE API # 30.025-26307.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	19S	36E	1980			1980	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE


Type of Release B/w & F/w	Volume of Release BBls. 165	Volume Recovered BBls. 165
Source of Release Tubing	Date and Hour of Occurrence 9-8-10 @ 1930	Date and Hour of Discovery 9-8-10 @ 2000
Was Immediate Notice Given? <input type="checkbox"/> x Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Lucking	
By Whom? Jon Ammons	Date and Hour 9-9-10 @ 0800	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Potential tubing problem causing well to leak water. Upon learning of this, 3 vacuum trucks dispatched to location to begin cleaning spill. Spill was controlled & cleanup was complete. Currently awaiting a pulling unit to investigate potential problems with tubing & regulatory agency approval.

Describe Area Affected and Cleanup Action Taken.*
The vast majority of the water was contained, a small amount of the water did leak onto dirt road. Both areas were cleaned up via vacuum trucks, dyke has been repaired.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon Ammons	Approved by ENV ENGINEER: District Supervisor: 	
Title: Manager	Approval Date: 09/22/10	Expiration Date: 11/22/10
E-mail Address: ammons17@yahoo.com	Conditions of Approval: SITE MUST BE DELINEATED VERTICALLY AND HORIZONTALLY TO CLEAN +1. REMEDIATION IF NECESSARY PER DELINEATION, SUBMIT FINAL C-141 BY 11-22-10.	Attached <input type="checkbox"/>
Date: 9-10-10 Phone: 575-393-8352		IRP-10-9-2613