

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 23 2010

HOBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	<i>Am tex</i>	Contact	<i>Bill Savage</i>
Address		Telephone No.	<i>432 - 770 - 0913</i>
Facility Name	<i>Dagger Lake 6 State # 2</i>	Facility Type	<i>Production Well</i>
Surface Owner	Mineral Owner		Lease No.

LOCATION OF RELEASE API # *30.025.27573.00.00*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>9</i>	<i>6</i>	<i>22S</i>	<i>33E</i>					

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	<i>BS + Oil</i>	Volume of Release	<i>5-7 BBL</i>	Volume Recovered	<i>0</i>
Source of Release	<i>open top water tank</i>	Date and Hour of Occurrence	<i>9.15</i>	Date and Hour of Discovery	<i>9.16</i>
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	<i>OCD 11 p.m.</i>		<i>8 a.m.</i>
By Whom?	<i>none</i>	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<i>none</i>		

If a Watercourse was Impacted, Describe Fully.*
none

Describe Cause of Problem and Remedial Action Taken.*
Trucker dumped load in tank causing tank to overflow spilling oil on ground behind tanks and west south in Pasture - Scraped up area


Describe Area Affected and Cleanup Action Taken.*
Area affected was west behind tanks and pasture south of location Scraped up Contamination and hauled to Lazy Ace land farm Sampled area - Field analysis clean took to lab for analysis

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>William J Savage</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>William J. Savage</i>		Approved by ENV ENGINEER: <i>Jeffrey Lehman</i> District Supervisor:	
Title: <i>President</i>	Approval Date: <i>09/24/10</i>	Expiration Date: <i>11/24/10</i>	
E-mail Address: <i>billsavage@verizon.net</i>	Conditions of Approval: <i>SUBMIT FINAL C-141 BY 11/24/10</i>		Attached <input type="checkbox"/>
Date: <i>9-23-2010</i>	Phone: <i>432-770-0913</i>	<i>IRP-10-9-2616</i>	

* Attach Additional Sheets If Necessary

Amtox Energy
 Lea ED State Battery #1
 SW 1/4 of SW 1/4
 S-16 T-19S R 34E
 Lea County
 September 22 2010



<u>Sample ID</u>	<u>Depth</u>	<u>Time</u>	<u>Reading</u>
S1	2-3'	12:15	5 x 20 = 100
S2	2-3'	12:25	5 x 20 = 100



CARDINAL LABORATORIES

101 East Marland, Hobbs, NM 88240
(575) 393-2326 FAX (575) 393-2476

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST


Company Name: 3K oil and gas				BILL TO				ANALYSIS REQUEST															
Project Manager: Jacobs Mulancom				P.O. #: 3418																			
Address: 101 E. Panther				Company: Amtex Energy																			
City: Jal		State: N.M.		Zip: 88252		Attn: Energy																	
Phone #: 575-395-2654		Fax #: 575-395-2164		Address:																			
Project #: #135		Project Owner: Amtex Operating		City: Midland																			
Project Name: Dagger Lake 6 state #2				State: TX																Zip: 79702-3418			
Project Location: Dagger Lake 6 state #2				Phone #:																			
Sampler Name:				Fax #:																			
FOR LAB USE ONLY																							
Lab I.D.	Sample I.D.	(G)RAB OR (C)OMP.	# CONTAINERS	MATRIX					PRESERV.			SAMPLING		DATE	TIME	CL	TPH	BTEX					
				GROUNDWATER	WASTEWATER	SOIL	OIL	SLUDGE	OTHER	ACID/BASE	ICE / COOL	OTHER											
H2D898-1	S1 6"-1'	B	1			X								9-22	9:35								
2	S2 6"-1'	B	1			X								9-22	9:41								
3	S3 6"-1'	B	1			X								9-22	9:47								
4	S4 6"-1'	B	1			X								9-22	10:00								

PLEASE NOTE: Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the client for the analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or subsidiaries or a part or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise.

Relinquished By:	Date:	Received By:	Phone Result:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Add'l Phone #:
	Time:		Fax Result:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Add'l Fax #:
Relinquished By:	Date: 9/22/10	Received By: Jodi Henson	REMARKS:			
Delivered By: (Circle One)	Time: 3:30	Sample Condition:	Email Results to			
Sampler - UPS - Bus - Other:	20	Cool Intact	Jacobs @ 3K oil and gas.com			
		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				
		<input type="checkbox"/> Yes <input type="checkbox"/> No				
		CHECKED BY: JH				

#216

Amteck Operating
 Dagger Lake 6 state #2
 9.22.2010



	Depth	Time	Reading
S1 -	6"-1	9:35	16x20 = 320
S2 -	↓	9:41	12x20 = 240
S3 -		9:47	12x20 = 240
S4 -		10:00	12x20 = 240



CARDINAL LABORATORIES

101 East Marland, Hobbs, NM 88240
(575) 393-2326 FAX (575) 393-2476

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Company Name: <u>3K Oil and Gas</u>			BILL TO			ANALYSIS REQUEST																					
Project Manager: <u>Jacob Melancon</u>			P.O. #: <u>3418</u>																								
Address: <u>101 E. Panther</u>			Company: <u>Amtec Energy</u>																								
City: <u>Jal</u> State: <u>N.M.</u> Zip: <u>88252</u>			Attn:																								
Phone #: <u>575-395-2654</u> Fax #: <u>505-395-2162</u>			Address:																								
Project #: <u>#136</u> Project Owner:			City: <u>Midland</u>																								
Project Name: <u>Lea ED State Battery #1</u>			State: <u>TX</u> Zip: <u>79702-3418</u>																								
Project Location: <u>state Battery #1</u>			Phone #:																								
Sampler Name: <u>Jacob Melancon</u>			Fax #:																								
FOR LAB USE ONLY																											
Lab I.D.		Sample I.D.		(#GRAB OR (C)OMP. # CONTAINERS	MATRIX						PRESERV.			SAMPLING													
					GROUNDWATER	WASTEWATER	SOIL	OIL	SLUDGE	OTHER :	ACID/BASE	ICE / COOL	OTHER :	DATE	TIME												
<u>H20899-1</u>		<u>S1 2-3'</u>		<u>5</u>			<u>X</u>						<u>9-22</u>	<u>12:15</u>													
<u>2</u>		<u>S2 2-3'</u>		<u>5</u>			<u>X</u>						<u>9-22</u>	<u>12:25</u>													

PLEASE NOTE: Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the client for the analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In the event that Cardinal be liable for incidental or consequential damages including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or its licensees arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise.

Relinquished By:	Date:	Received By:	Phone Result: <input type="checkbox"/> Yes <input type="checkbox"/> No	Add'l Phone #:
	Time:		Fax Result: <input type="checkbox"/> Yes <input type="checkbox"/> No	Add'l Fax #:
Relinquished By: <u>Jacob Melancon</u>	Date: <u>9/22/10</u>	Received By: <u>Jodi Mensor</u>	REMARKS:	
Delivered By: (Circle One)	Time: <u>3:30</u>	Sample Condition	CHECKED BY: <u>JM</u>	
Sampler - UPS - Bus - Other:		Cool <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Email Results to:	
		Intact <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<u>Jacob E 3K oil and gas.com</u>	

#26