


District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-05710

Release Notification and Corrective Action

nMCB1027335047

OPERATOR

Initial Report Final Report

Name of Company	Endurance Resources LLC 270329	Contact	Randall Harris
Address	P.O. Box 1466 Artesia, NM 88211	Telephone No.	575.703.0722
Facility Name	State E	Facility Type	Production Battery

Surface Owner	State of New Mexico	Mineral Owner	Endurance Resources LLC	Lease No.	E-6017
---------------	---------------------	---------------	-------------------------	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Fect from the	North/South Line	Fect from the	East/West Line	County
E	2	19 S	31 E	330	North	330	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil & Water	Volume of Release	50	Volume Recovered	in progress
Source of Release	Water Tank	Date and Hour of Occurrence	? time 9/27/10	Date and Hour of Discovery	10:AM 9/27/10
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Randall Harris	Date and Hour	2:45 PM 9/27/2010		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Lightning strike hit 210 bbl water tank. After discovery, vacuum truck on location picking up water and oil. Backhoe removing contaminated soil.

Describe Area Affected and Cleanup Action Taken.*
Area inside berm covered. Outside berm some oil and water on north, west and south side extending approx 10-15' but remained within pad area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Randall Harris	Approved by <i>Mike Bratcher</i> District Supervisor	
Title: Geologist	Approval Date: SEP 30 2010	Expiration Date:
E-mail Address: rharrisnm@yahoo.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/27/10 Phone: 575 308.0722	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 10/30/10	

* Attach Additional Sheets If Necessary

PM4B1027335550

2RP-438

Bratcher, Mike, EMNRD

From: Randall Harris [rharrisnm@yahoo.com]
Sent: Monday, September 27, 2010 3:11 PM
To: Bratcher, Mike, EMNRD
Subject: Endurance Resources State E battery
Attachments: c141-State E battery-1.DOC

Mike,

Attached is c141 on the lightning strike on our State E battery. We will keep on it until cleaned up. I will keep you informed and will call you when soil has been removed from inside dike.

Randall Harris
Endurance Resources LLC
575.308.0722
Cell. 575.365.7747