

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
RECEIVED
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 8823	Telephone No. 575-390-4186
Facility Name EBDU SWD	Facility Type SWD

Surface Owner Stephens	Mineral Owner NMOCD	Lease No. 30-025-28011
------------------------	---------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	13	21S	37E	660'	FSL	2100'	FEL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release PW	Volume of Release 250	Volume Recovered 240
Source of Release cattle opened valve	Date and Hour of Occurrence 09/20/2010 430pm	Date and Hour of Discovery 09/20/2010 430pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leaking	
By Whom? Natalie Gladden	Date and Hour 09/21/2010 8am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Valve on DP cell opened by cattle when fence was down during reconstruction of facility. This facility is lined.

Describe Area Affected and Cleanup Action Taken.*
Pea gravel was removed to inspect the integrity of the liner, liner was not compromised. New pea gravel was added with the old, to build the inside of the battery floor up. Apache requests at this time, due to liner that this spill be closed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	 Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: EHS Environmental Tech	Approval Date: 10.12.10	Expiration Date: _____
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: _____	Attached <input type="checkbox"/> IRP# 10.10.2630
Date: 10/12/10 Phone: 575-390-4186		

* Attach Additional Sheets If Necessary

N L 045 1028753839
P L 045 1028754372