

C-141

FINAL

REPORT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GC Federal #27 Tank Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No.	NMNM-029405B (API#) 30-025-39264

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	20	17S	32E	990	South	2200	West	Lea

Latitude 32 48.959 Longitude 103 47.383

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15bbbls	Volume Recovered	14bbbls
Source of Release	1" nipple broke on bottom of filter pot	Date and Hour of Occurrence	10/20/2010	Date and Hour of Discovery	10/20/2010 2:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A 1" nipple broke on the bottom of the filter pot allowing water to release into containment. All fittings were replaced with new steel fittings to prevent recurrence.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 15bbbls or produced was released from the broken 1" nipple on the filter pot and all fluid was contained inside the dike walls of the facility which is lined with a 40 mil liner. The released fluid was recovered with a vacuum truck and disposed of appropriately. Any contaminated gravel will be removed and hauled to disposal. Clean gravel will be added as needed. We will follow up with a C-141 Final Report.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Josh Russo	Approved by District Supervisor	
Title:	HSE Coordinator	Approval Date:	11.1.10
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	—
Date:	10/29/2010	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>
			IRP-10.10.2639

* Attach Additional Sheets If Necessary

nLWT 1030556022
PLWT 1030557381