


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

hMLB1030952075

OPERATOR

Initial Report Final Report

Name of Company OXY USA	<i>16696</i>	Contact Kelton Beaird
Address 1502 W. Commerce Carlsbad, NM 88220		Telephone No. (O) 575-628-4100
Facility Name Lakewood 15-1		Facility Type Oil Well with Battery
Surface Owner Private	Mineral Owner	Lease No. API: 3001533574

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	15	19S	26E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 54bbls	Volume Recovered 25bbls
Source of Release Tank Battery	Date and Hour of Occurrence	Date and Hour of Discovery 10-17-10 @ 1 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (Left message and sent e-mail)	
By Whom? Kelton Beaird (HES-Oxy)	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Tank Battery corroded and leaked. The tank was emptied and removed from service

Describe Area Affected and Cleanup Action Taken.*
Area affected is inside the containment walls around the battery and a small amount east of the battery in the pasture approx. 21' X 12'. The area will be delineated and a clean-up plan will be submitted for approval

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird	Approved by District Supervisor:	
Title: HES Specialist	Approval Date: NOV 05 2010	Expiration Date:
E-mail Address: kelton_beaird@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-18-10	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 12/6/2010	

* Attach Additional Sheets If Necessary

2RP-464

Bratcher, Mike, EMNRD

From: Kelton_Beaird@oxy.com
Sent: Monday, October 18, 2010 10:44 AM
To: Bratcher, Mike, EMNRD
Subject: Lakewood 15-1 leak

Importance: High

Mike,

Had a reportable leak on the Lakewood 15-1 tank battery. I will send a C-141 ASAP.

Thanks,

**Kelton Beaird
HES Specialist
MidCon Southwest
Carlsbad, NM
Office: 575-628-4121
Cell: 575-390-1903
Fax: 575-628-4125**