

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources **RECEIVED**
Oil Conservation Division
1220 South St. Francis Dr. NOV 10 2010
Santa Fe, NM 87505 **HOBBSOCD**

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	Plains Pipeline, LP	Contact	Jason Henry
Address	2530 Hwy 214 - Denver City, Tx 79323	Telephone No.	(575) 441-1099
Facility Name	Jal Station E Header Valve	Facility Type	Tank Farm

Surface Owner	Plains	Mineral Owner		Lease No.	
---------------	--------	---------------	--	-----------	--

LOCATION OF RELEASE

APN 30-025-12803

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	5	26S	37E					Lea

Latitude N 32.07833330° Longitude W 103.17805560°

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	25 bbls	Volume Recovered	24 bbls
Source of Release	Valve	Date and Hour of Occurrence	10/27/2010 @ 12:00	Date and Hour of Discovery	10/27/2010 @ 12:00
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson		
By Whom?	Jason Henry	Date and Hour	10/28/2010 @ 13:25 (voice message)		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
During a pipe replacement at Jal Station, a motor valve inadvertently opened releasing approximately 25 bbls of oil into an open ditch line. A vacuum truck was utilized to recover the oil from the ditch line.

Describe Area Affected and Cleanup Action Taken.*
Released crude oil pooled in an open ditch line on the south side of the valve and was recovered with a vacuum truck. Impacted area will be remediated per applicable guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Jason Henry</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name:	Jason Henry	Approved by District Supervisor:	<i>L. Johnson</i> ENVIRONMENTAL ENGINEER
Title:	Remediation Coordinator	Approval Date:	10-10-10
E-mail Address:	jhenry@paalp.com	Expiration Date:	2-10-2011
Date:	11-10-2010	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(575) 441-1099	SUBMIT FINAL C-141	
		IRP# 11-10-2647	

* Attach Additional Sheets If Necessary

n LWT 1031630801
P LWT 1031631135