

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

JUL 08 2010

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez	
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238	
Facility Name Mad Dog 15 Federal #1	Facility Type <input type="checkbox"/> Gas Well	
Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>

LOCATION OF RELEASE

API # 30-025-36778-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	23S	34E	660	South	660	East	Lea County, NM

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15 BPW	Volume Recovered <input type="checkbox"/> 0 BPW
Source of Release Hairline split in water transfer line	Date and Hour of Occurrence 6-1-2010 7:00 AM	Date and Hour of Discovery 6-1-2010 7:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Trishia BadBear (BLM-Hobbs)	
By Whom? <input type="checkbox"/> Roger Hernandez	Date and Hour <input type="checkbox"/> 6-1-2010 9:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

WATER @ 280'



Describe Cause of Problem and Remedial Action Taken.*

15 bbls of Produced water was released due to a hairline fracture in a transfer line.

Describe Area Affected and Cleanup Action Taken.*

Area impacted was 40' in diameter with some overspray; soil samples of affected area, horizontally and vertically, will be taken for analysis. The remediation will be based off of lab results. The transfer line was scheduled for replacement June 2, 2010; it has been replaced at this time.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Don Mayberry	Approved by <input type="checkbox"/> District Supervisor: 	
Title: Superintendent	Approval Date: 07/08/10	Expiration Date: 09/08/10
Date: June 4, 2010 Phone: 575-748-5235	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>

C-141 BY 09/08/10.

IRP-11-10-2644

* Attach Additional Sheets If Necessary