

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUL 28 2010

HOBBSOCD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report  Final Report

Name of Company Oxy USA WTP	Contact Dusty Wilson
Address 1017 W. Stanolind Rd	Telephone No. (575) 397-8247
Facility Name South Mattix Ellenburg Battery	Facility Type Gathering

Surface Owner Bill Grobe	Mineral Owner	Lease No. NM-19582
--------------------------	---------------	--------------------

**LOCATION OF RELEASE** *NABBY WELZ MLMU 249*  
*API # 30.025.11083.00.00*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	15	24s	37e					Lea

Latitude N32.13.022 Longitude W103.08.962

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 15 bo	Volume Recovered 5 bo
Source of Release Power failure at air compressor for free water KO	Date and Hour of Occurrence 07/10/2010 1100 am	Date and Hour of Discovery same
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Leking and Trish Badbear	
By Whom? Dusty Wilson	Date and Hour 07/13/2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse. n/a	

If a Watercourse was Impacted, Describe Fully.\*

N/A


Describe Cause of Problem and Remedial Action Taken.\*

Power failure at air compressor for free water knock out at Battery caused tanks to run over, and putting above listed fluids out and onto location. Remediation efforts are in progress, and will be determined according to NMOCD requirements. Vac truck was deployed and recovered most of released fluids.

Describe Area Affected and Cleanup Action Taken.\*

Remediate to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dusty L. Wilson	APPROVED BY: <i>Jeffrey Leking</i> Approved by District Supervisor:	
Title: HES Specialist	Approval Date: 07/28/10	Expiration Date: 09/28/10
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval: SUBMIT FINAL C-141 BY 09/28/10.	Attached <input type="checkbox"/>
Date: <del>06/23/2010</del> 07/21/10 Phone: (575) 397-8210		IRP-11-10-2649

- Attach Additional Sheets If Necessary