

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
NOV
DEC 19 2010
HOBBSDO
Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name North Skaggs Injection Station	Facility Type Injection Station

Surface Owner NMOCD BLM FED	Mineral Owner BLM	Lease No. 3002506089
--	-------------------	----------------------

LOCATION OF RELEASE

SEMU Eumont #A2

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	13	20S	37E	660	South	1980	West	Lea

Latitude 32 34.055 N Longitude 103 12.431 W

WTR 60

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 12	Volume Recovered 8
Source of Release Injection Line	Date and Hour of Occurrence 11/18/10 8:30 am	Date and Hour of Discovery 11/18/10 9 a
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD & BLM	
By Whom? Jesse Sosa	Date and Hour 11/19/10 8:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
MSO found a leak on a steel 1 inch (25+ years) line at the header. MSO shut in and isolated injection line. Release was due to internal corrosion. Line will be replaced before putting well back into service.

Describe Area Affected and Cleanup Action Taken.*
Total release was 12 BPW. A vacuum truck was called out and recovered 8 BPW. Affected area was 50 feet X 80 feet, 90% on caliche pad. Sample area and submit work plan for clean up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	 Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: HSER Lead	Approval Date: 11.19.10	Expiration Date: 3.19.10
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval:	
Date: 11/19/2010 Phone: (505)391-3126	Submitted Final C-141 w/Docs 84 Attached <input type="checkbox"/> IRP# 11-10-2657	

* Attach Additional Sheets If Necessary

nLWT 1032639357
pLWT 1032639715