

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
DEC 01 2010  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-37679

**Release Notification and Corrective Action**

NMLB1034347624

**OPERATOR**

X Initial Report  Final Report

Name of Company EOG Resources, Inc.	7377	Contact Renee Jarratt
Address P. O. Box 2267, Midland, TX 79702		Telephone No. 432-686-3684
Facility Name W. Brushy Draw #2 Fed 1H		Facility Type Flow Line

Surface Owner FED	Mineral Owner	Lease No.
-------------------	---------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	25s	29E	270	N	405	W	Eddy

Latitude\_32 06.143\_ Longitude\_103 58.841\_

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 80 bbls	Volume Recovered 0
Source of Release Cut Flowline	Date and Hour of Occurrence 11/30/10 7:00 am	Date and Hour of Discovery 11/30/10 8:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes X No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
COG contracted Production Specialty to remove their flowline, Production Specialty cut into EOG's line by mistake causing release. Production Specialty has accepted all financial responsibility for the cleanup.

Describe Area Affected and Cleanup Action Taken.\*  
The release on the lease road measured an approximate area of 16' x 432' with intermittent puddles, the fluid traveled off the lease road in two locations with one measuring approximately 3' x 359' & the other measuring 3' x 320'. COG has been in contact with Petro Tech Environmental for the clean up.  
Retra

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Renee Jarratt	Approved by District Supervisor:	
Title: Environmental Rep	Approval Date: DEC 09 2010	Expiration Date:
E-mail Address: renee_jarratt@egoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/01/10 Phone: 432-686-3684	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: JAN 9, 2011	

\* Attach Additional Sheets If Necessary

Fed # 11NU015TG

2RP-496

**Bratcher, Mike, EMNRD**

---

**From:** Renee\_Jarratt@eogresources.com  
**Sent:** Wednesday, December 01, 2010 10:03 AM  
**To:** Bratcher, Mike, EMNRD; james\_amos@blm.gov  
**Cc:** pellis@conchoresources.com; jrusso@conchoresources.com  
**Subject:** OCD C-141 form  
**Attachments:** Scan001.PDF

Mike,

As per our conversation this morning, this is what I have filled out on the C-141 form. If you need anything else from me please call. I have also attached the information that Josh Russo from Concho sent to me.

Thanks,

Renee' Jarratt  
EOG Resources  
432-686-3684

**Reneé Jarratt** | Environmental Representative | EOG Resources, Inc. | 432-686-3684 |  
[renee\\_jarratt@eogresources.com](mailto:renee_jarratt@eogresources.com)

*(See attached file: Scan001.PDF)*

# LEAK AND SPILL REPORT



## 1. Reporting

Reported by	<u>Cruz Ortega</u>	To	<u>Pat Ellis</u>	Time	<u>11:00</u>
Reported by	_____	To	_____	Time	_____
Reported by	_____	To	_____	Time	_____
Reported by	_____	To	_____	Time	_____

## 2. Location of Incident

GPS Coordinates of Spill 32 06.143 - 103 58.841  
Origination of Spill 4" EOG poly line

Legal description and location of closest well \_\_\_\_\_

Driving Directions to Spill \_\_\_\_\_

## 3. When Incident Occurred

Date 11/30/2010 Time 7:00 a.m.

## 4. Product Released: Type and Volume

Produced Water - 80bbls

## 5. Product Recovered: Type and Volume

none

## 6. Description of Incident and Cause

Production Specialty crew cut into wrong line causing a release of produced water. Production Specialty has accepted financial responsibility for the cleanup of the release.

## 7. Additional Information (dike lining, size and location of contamination, etc.)

The release on the lease road measured a total area of 16' x 432' with intermittent puddles, the fluid traveled off the lease road in two locations with one measuring 3' x 359', and the other measuring 3' x 320'.

## 8. Repair Procedure

## 9. Cleanup Completed

## 10. Cleanup to be Completed upon HSE Approval

Cleanup of spill area, closure of site

## 11. Measures Taken to Prevent Reoccurrence

Pay attention to the job at hand, be cautious

## **Bratcher, Mike, EMNRD**

---

**From:** Joshua Russo [jrusso@conchoresources.com]  
**Sent:** Tuesday, November 30, 2010 4:23 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Pat Ellis  
**Subject:** EOG Resources poly line release

Mr. Bratcher,

I wanted to give you a quick heads up regarding the situation that you previously spoke with Ike Tavarez about earlier on the phone. You will be receiving a call from Renee from EOG Resources giving you immediate notification of a release that occurred involving a Production Specialties Inc. crew (Production Specialties was picking up a line for COG and cut into an EOG produced water line). Production Specialties will be taking financial responsibility for this cleanup which will be handled by Tetra Tech.

The release was along a lease road with GPS coordinates of 32 06.143 – 103 58.841.

Thanks you,


### **Joshua Russo**

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.


# VICINITY MAP



SEC. 27 TWP. 25-S RGE. 29-E  
 SURVEY N.M.P.M.  
 COUNTY EDDY  
 DESCRIPTION 270' FNL & 405' FWL  
 ELEVATION 3018.5'  
 OPERATOR EOG RESOURCES, INC.  
 LEASE WEST BRUSHY 27 FED. #1H

SCALE: 1" = 2 MILES

Asel Surveying



P.O. BOX 393 - 310 W. TAYLOR  
 HOBBS, NEW MEXICO - 575-393-9146

DIRECTIONS FROM THE INTERSECTION OF U.S. HWY. #285 AND BLACK RIVER VILLAGE ROAD IN MALAGA, GO SOUTH ON U.S. HWY. #285 FOR 12.6 MILES, TURN LEFT ON COUNTY ROAD #725 (WHITETHORN ROAD) AND GO EAST NORTHEAST FOR 4.0 MILES, TURN LEFT ON LEASE ROAD AND GO NORTHEAST ALONG PIPELINE FOR 2.0 MILES, TURN LEFT AND GO NORTH ON CALICHE ROAD FOR 1.8 MILES TO PROPOSED NEW ROAD, GO EAST (ON PROPOSED NEW ROAD) FOR 192 FEET TO LOCATION.