



# GW - 028 MONITORING REPORT Annual GW Monitoring Report MAPS (Feb 2011)



- LEGEND:
- ◆ MONITORING WELL
  - RECOVERY WELL
  - IRRIGATION WELL
  - ABANDONED WELL
  - VALLEY FILL AQUIFER POTENTIOMETRIC SURFACE CONTOURS



NAVAJO REFINING COMPANY  
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO  
FIRST SEMIANNUAL EVENT 2010 (MAR-APR)

**VALLEY FILL AQUIFER  
POTENTIOMETRIC SURFACE MAP**



FIGURE  
**4**