



GW - 028 MONITORING REPORT Annual GW Monitoring Rep MAPS (Feb 2011)



- LEGEND:
- ◆ MONITORING WELL
 - RECOVERY WELL
 - IRRIGATION WELL
 - ABANDONED WELL
 - VALLEY FILL AQUIFER POTENTIOMETRIC SURFACE CONTOURS



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
SECOND SEMIANNUAL EVENT 2010 (SEP-OCT)

VALLEY FILL AQUIFER
POTENTIOMETRIC SURFACE MAP



FIGURE
6