



GW - 028 MONITORING REPORT Annual GW Monitoring Rep MAPS (Feb 2011)



- LEGEND:
- ARSENIC GROUNDWATER EXCEEDANCE AREA
 - ◆ MONITORING WELL
 - RECOVERY WELL
 - IRRIGATION WELL
 - ABANDONED WELL



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2010 ANNUAL GROUNDWATER REPORT
**ARSENIC CRITICAL GROUNDWATER
SCREENING LEVEL EXCEEDANCE AREAS
SECOND SEMI-ANNUAL EVENT 2010**



FIGURE
12