




GW - 028 MONITORING REPORT Annual GW Monitoring Rep MAPS (Feb 2011)



LEGEND:

- NAPHTHALENE GROUNDWATER EXCEEDANCE AREA
- MONITORING WELL
- RECOVERY WELL
- IRRIGATION WELL
- ABANDONED WELL



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2010 ANNUAL GROUNDWATER REPORT

NAPHTHALENE CRITICAL GROUNDWATER
SCREENING LEVEL EXCEEDANCE AREAS
SECOND SEMI-ANNUAL EVENT 2010



FIGURE

16