

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nkmw 1106139339*

**OPERATOR**

Initial Report  Final Report

Name of Company	Lime Rock Resources <i>255733</i>	Contact	Michael Barrett
Address	P.O. Box 2147 Roswell, NM 88202-2147	Telephone No.	575-623-8424
Facility Name	Staley State #6	Facility Type	Oil Well
Surface Owner	C.O.G.	Mineral Owner	State
		Lease No.	30-015-37056

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
3	30'	17S	28E	1960'	FSL	990'	FWL	Eddy

Latitude *32.803136432* Longitude *104.220424329*

**NATURE OF RELEASE**

Type of Release	Acid & Fresh Water	Volume of Release	214 bbls	Volume Recovered	30 bbls
Source of Release	Broken Nipple on Acid Truck	Date and Hour of Occurrence	2/18/11 @ 10:00 am	Date and Hour of Discovery	2/18/11 @ 10:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Randy Dade		
By Whom?	Jerry Smith	Date and Hour	2/18/11 @ 11:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
N/A					
Describe Cause of Problem and Remedial Action Taken.*					
Nipple broke on bottom of the acid truck. P/U standing fluid.					
Describe Area Affected and Cleanup Action Taken.*					
Ground is rocky with loose soil. Spread 2000 #'s soda ash and flushed with 130 bbls fresh water. P/U 40 bbls of flush.					

**RECEIVED**  
FEB 23 2011  
NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Barrett</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Michael Barrett	Approved by District Supervisor <i>Michael Barrett</i>	
Title: Production Supervisor	Approval Date: <i>3/7/11</i>	Expiration Date:
E-mail Address: <i>mbarrett@limerockresources.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/22/11	Phone: 575-623-8424	

\* Attach Additional Sheets If Necessary

*Jerry Smith: 505-918-0556*

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

*4/7/11*

*2RP-624*