


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

17KMW/10674/082

OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Moose Federal 23	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015- 25332 <i>35755</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	23	16S	28E					Eddy

Latitude 32 54.350 Longitude 104 09.130

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	40bbls	Volume Recovered	35bbls
Source of Release	Stock tank	Date and Hour of Occurrence	02/26/2011	Date and Hour of Discovery	02/26/2011 8:30 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher—OCD		
By Whom?	Josh Russo	Date and Hour	02/28/2011 9:38 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A hole developed in a stock tank at the tank battery. The tank has been removed from service.

Describe Area Affected and Cleanup Action Taken.*
Initially 40bbls of oil was released from the stock tank and we were able to recover 35bbls with a vacuum truck. The entire release was contained inside the berm walls of the facility and measured an area of 20' x 50' around the tanks and toward the heaters. The contaminated soil has been removed and all free fluids have been picked up. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD / BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	Expiration Date:
E-mail Address:	jrusso@conchoresources.com	Conditions of Approval:	
Date:	03/02/2011	Phone:	432-212-2399
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2 RP 636

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Friday, March 04, 2011 3:30 PM
To: Bratcher, Mike, EMNRD; terry_gregston@nm.blm.gov
Cc: Pat Ellis; james_amos@nm.blm.gov; Tavarez, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com
Subject: C-141 - Moose Federal TB
Attachments: MOOSE TANK BATTERY -- DATE OF RELEASE -- 02-21-2011.PDF; MOOSE FEDERAL TANK BATTERY -- DATE OF RELEASE -- 02-26-2011.PDF

Please see attached two C-141 Initial Reports for spills that occurred at the Moose Federal Tank Battery.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: tgregsto@blm.gov
Sent: Friday, March 04, 2011 6:47 PM
To: Joshua Russo
Cc: Tavaréz, Ike; james_amos@nm.blm.gov; Dorey, Kim; Bratcher, Mike, EMNRD; Pat Ellis; terry_gregston@nm.blm.gov; tom.k.franklin@tetrattech.com
Subject: Re: C-141 - Moose Federal TB: Question? and correct API #

I have received your notification of two spills contained within the berms of an unlined facility. Federal tracking numbers 11NU044TG and 11NU045TG respectively. Do these spills overlap in impact footprint, or do they affect two separate areas within the containment?

Also, the well name and API# referenced on the C-141 reports is a plugged and abandoned well. It would probably be better to tie this spill to the active well on the same pad. Correct well name and API: Moose 23 Federal 1Y, API #3001535755.

Terry Gregston
Environmental Protection Specialist
Bureau of Land Management
620 E. Greene St.
Carlsbad, NM 88220
Office (575) 234-5958
Fax (575) 234-5927

Joshua Russo <jrusso@conchoresources.com>

03/04/2011 03:29 PM

To "Bratcher, Mike, EMNRD" <mike.bratcher@state.nm.us>, "terry_gregston@nm.blm.gov" <terry_gregston@nm.blm.gov>

cc Pat Ellis <PEllis@conchoresources.com>, "james_amos@nm.blm.gov" <james_amos@nm.blm.gov>, "Tavaréz, Ike" <Ike.Tavaréz@tetrattech.com>, "Dorey, Kim" <Kim.Dorey@tetrattech.com>, "tom.k.franklin@tetrattech.com" <tom.k.franklin@tetrattech.com>

Subject C-141 - Moose Federal TB

Please see attached two C-141 Initial Reports for spills that occurred at the Moose Federal Tank Battery.

Thank you,

Joshua Russo
HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

[attachment "MOOSE TANK BATTERY -- DATE OF RELEASE -- 02-21-2011.PDF" deleted by Terry G Gregston/CFO/NM/BLM/DOI]

[attachment "MOOSE FEDERAL TANK BATTERY -- DATE OF RELEASE -- 02-26-2011.PDF" deleted by Terry G Gregston/CFO/NM/BLM/DOI]