

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DEC 02 2010

Form C-141
Revised October 10, 2003

HOBBSD

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Targa Midstream Services L P	Contact: Gary Maricle 575.394.2534, Chuck Tolsma 575.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (575) 394-2534
Facility Name: Eunice Gas Plant	Facility Type: Natural Gas Gathering System

Surface Owner: Bill Sims	Mineral Owner:	Lease No.
--------------------------	----------------	-----------

LOCATION OF RELEASE

NEAR BY JV BAKER EXPL STORAGE
API # 30.025-21497.00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	27	22S	37E					Lea

Latitude 32.3592N Longitude 103.1419

NATURE OF RELEASE

Type of Release: Installing new pipe and working on old sites	Volume of Release: UNK	Volume Recovered: NONE
Source of Release: 2-8" LINE BREAKS	Date and Hour of Occurrence: NA	Date and Hour of Discovery: NA
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Twin 8 inch natural gas gathering lines developed leaks from corrosion. Lines were shut in and 300 feet of 6 inch poly line was inserted into each of the steel lines. Contaminated soil will be excavated and disposed of in an OCD approved landfarm.

Describe Area Affected and Cleanup Action Taken.*

The two 8 inch steel lines are used for casing for the 6 inch poly lines. Areas of contamination will be addressed and excavated and sampled to insure compliance with OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	ENV ENGINEER: Approved by District Supervisor: <i>Sheffrey Perry</i>	
Title: Training Specialist	Approval Date: 12/03/10	Expiration Date: 02/03/11
E-mail Address: dembrey@targaresources.com	Conditions of Approval: SUBMIT FINAL C-141 BY 02/03/11.	Attached <input type="checkbox"/>
Date: December 1, 2010 Phone: (432) 688-0546		IRP-03-11-2691

* Attach Additional Sheets If Necessary