

RECEIVED JUN 16 2010

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

nkmw1035732429

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Marshall APH Battery	API Number 30-015-28543	Facility Type Battery
	Order Number 2RP-	
Surface Owner Fee	Mineral Owner Federal	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	9	19S	25E	1980	North	1980	West	Eddy

Latitude N33.13240 Longitude W104.13323

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30	Volume Recovered 0
Source of Release Check Valve Failure	Date and Hour of Occurrence 06/06/2010	Date and Hour of Discovery 06/06/2010 - PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 06/16/2010 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Upon Discovery of the spill the problem was isolated. A vacuum truck was dispatched to recover any standing fluids.		
Describe Area Affected and Cleanup Action Taken.* An approximate size of 15' x 75' was impacted. The impacted area is located along the back side of the berm. Soil from the pooling areas will be excavated and disposed of at an NMOCD approved facility. Vertical and horizontal delineation samples will taken and analysis ran for TPH, BTEX and Chlorides once all contaminated material has been removed. Depth to Ground Water: <100' (approx. 260', per New Mexico Office of the State Engineer); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Based on site ground water quality and enclosed analytical results.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>A Trujillo</i>	Approved by District <i>Signed By Mike Bratcher</i>	
Printed Name: Amanda Trujillo	Approval Date: <i>3/21/11</i>	Expiration Date:
Title: Environmental Scientist	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
E-mail Address: atrujillo@yatespetroleum.com	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	
Date: Wednesday, June 16, 2010 Phone: 575-748-4310	<i>4/21/11</i>	

* Attach Additional Sheets If Necessary

PROPOSAL NOT LATER THAN:

2RP-530

Bratcher, Mike, EMNRD

From: Amanda Trujillo [atrujillo@yatespetroleum.com]
Sent: Wednesday, June 16, 2010 5:19 PM
To: Bratcher, Mike, EMNRD
Cc: Jerry Fanning
Subject: Marshall APH Battery
Attachments: Marshall APH Battery.pdf

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Marshall APH Battery
Sec. 9, Township 19 South, Range 25 East
Eddy County
Date of Release: 06/06/10
Approximately 30 barrels of produced water were released 0 barrels recovered
Cause of release has been isolated and repairs are in progress
Vacuum truck on site recovered standing fluids
Site will be evaluated and a work plan for remediation will be submitted for consideration.
Attached is the C-141

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com