

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nMLB1025648019

OPERATOR

Initial Report Final Report

Name of Company OXY USA	Contact Kelton Beard
Address 1502 W. Commerce Carlsbad, NM 88220	Telephone No. (O) 575-628-4100
Facility Name Airport 35-1	Facility Type Well with Battery

Surface Owner State	Mineral Owner State	Lease No. 3001530379
---------------------	---------------------	----------------------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	35	22S	26E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 40bbls/oil 5bbls/water	Volume Recovered 30bbls
Source of Release Storage Tank	Date and Hour of Occurrence	Date and Hour of Discovery 4-4-10 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD (left message)	
By Whom? Kelton Beard	Date and Hour 4-5-10 9:46am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*
Tank Bottom corroded causing leak. The tank was drained and taken out of service

Describe Area Affected and Cleanup Action Taken.*
As approved by Mike Bratcher, material removed is as follows: 8' at test point A, 4' at test point B, 2' at test point C, and 4' at test point D. Clean-like material was used for backfill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beard	Signed By: Approved by District Supervisor.	
Title: HES Specialist	Approval Date: 3/29/2011	Expiration Date: N/A
E-mail Address: kelton_beard@oxy.com	Conditions of Approval: N/A Final	Attached <input type="checkbox"/>
Date 10-27-10		

* Attach Additional Sheets If Necessary

2RP-432