

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

III - 8 2009

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-29252 Release Notification and Corrective Action



N. KMEW 1108956328 OPERATOR Initial Report Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Cotton Draw Unit #76	Facility Type <input type="checkbox"/> Gas Well
Surface Owner	Mineral Owner
Lease No. <input type="checkbox"/>	

LOCATION OF RELEASE

Unit Letter	Section 1	Township 25S	Range 31E	Feet from the 1650	North/South Line South	Feet from the 660	East/West Line West	County Eddy County
-------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	-----------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 8 bbls	Volume Recovered <input type="checkbox"/> 0 bbls
Source of Release Split in 3" poly line	Date and Hour of Occurrence 6-23-09 12:01 PM	Date and Hour of Discovery 6-23-09 12:01 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Trish BadBear (BLM - Lea County)	
By Whom? <input type="checkbox"/> Ernie Duran, Asst. Production Foreman	Date and Hour <input type="checkbox"/> 6-25-09 12:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* 3" produced poly water line off the production separator over to SWD station had split on pipe releasing produced water. Root cause was a dump valve malfunctioned over pressuring the line resulting in the leak and over spray of vegetation and terrain. Spill was approximately 8 bbls.		
Describe Area Affected and Cleanup Action Taken.* Sprayed an area about 40'x50' but there was not standing water as it was spraying a fine mist. Raked area, tiled, and fertilized.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Roger Hernandez	Signed By:  Approved by <input type="checkbox"/> District Supervisor	
Title: Production Foreman	Approval Date: <u>3/30/11</u>	Expiration Date:
Date: June 25, 2009 Phone: 575-748-5238	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY: 4/30/11

2RP-678