


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-23504

Release Notification and Corrective Action

nKmw 1109427459

258462

OPERATOR

Initial Report Final Report

Name of Company	NADEL AND GUSSMAN HEYCO, LLC	Contact	Clay Stevens or Tammy R. Link
Address	PO Box 1936, Roswell 88202-1936	Telephone No.	(505) 623-6601
Facility Name	Eddy JP State #1	Facility Type	
Surface Owner	USA	Mineral Owner	State of New Mexico
		Lease No.	NMNM073240

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	36	18S	31E	750'	S	1980'	W	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	-37 bbls of oil	Volume of Release	37 bbls	Volume Recovered	-0-
Source of Release	Hole in bottom of tank	Date/Hour of Release	11/6/09 ?	Date/Hour Discovered	11/7/09 7 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher w/OCD in Artesia		
By Whom?	Clay Stevens	Date and Hour	7:30 am 11/9/09		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Hole in the bottom of tank, will empty and clean and determine whether to repair or replace.

Describe Area Affected and Cleanup Action Taken.*
Will arrange to dig up and haul off contaminated soil and remove, will have a sample of soil tested and then wait to hear from Mike Bratcher.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Tammy Link	Approved by District Supervisor	
Title: Engineering Tech	Approval Date: 3/30/11	Expiration Date:
E-mail Address: tlink@heycoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/9/09	Phone: (505)623-6601	

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY:

5/1/11

2RP-685

