

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

SEP 22 2009

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-015-36461  
AKMW 1109729911

OPERATOR  Initial Report  Final Report

Name of Company <b>Devon Energy</b>	Contact <b>Shannon Moss, Foreman</b>	
Address <b>6488 Seven Rivers Hwy – P.O. Box 250</b>	Telephone No. <b>575-748-5232</b>	
Facility Name <b>Laguna Salado Battery</b>	Facility Type <b>Gas</b>	
Surface Owner	Mineral Owner	Lease No.

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<b>22</b>	<b>23</b>	<b>29</b>					<b>Eddy</b>

Latitude **N 32.299221** Longitude **W 103.97480**

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>30 bbls</b>	Volume Recovered <b>0</b>
Source of Release <b>4" poly SWD line, extending from the Laguna Salado Battery to the Remuda Basin SWD, ruptured; releasing approximately 30 bbls of produced water.</b>	Date and Hour of Occurrence <b>09/15/09 – 9:30</b>	Date and Hour of Discovery <b>09-15-09 – 9:30</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Paul Evans – BLM OCD</b>	
By Whom? <b>Shannon Moss, Foreman</b>	Date and Hour <b>9:45</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* **At the Laguna Salado Battery, a road grader clipped a 4" poly SWD line, extending from the Laguna Salado Battery to the Remuda Basin SWD, thus causing it to rupture; releasing approximately 30 bbls of produced water.**

Describe Area Affected and Cleanup Action Taken.\* **50' x 50' Sandy Pasture – Valves closed and area bermed, Leak repaired and contaminated soil removed and hauled to disposal site.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mykol Horner</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Mykol Horner</b>	Approved by District Supervisor:	
Title: <b>Field Tech 1</b>	Signed By: <i>Mike Brando</i>	
E-mail Address: <b>mykol.horner@dvn.com</b>	Approval Date: <b>4/7/11</b>	Expiration Date:
Date: <b>09/18/09</b> Phone: <b>575-748-0160</b>	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	
	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**PROPOSAL NOT LATER THAN:**  
5/7/11