





LEGEND:

PSH THICKNESS	MONITORING WELL
0 - 1 FOOT	RECOVERY WELL
1 - 2 FEET	IRRIGATION WELL
2 - 3 FEET	ABANDONED WELL
>3 FEET	



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2010 ANNUAL GROUNDWATER REPORT
**PHASE SEPARATED HYDROCARBON
THICKNESS ISOPLETHS (FEET)**
FIRST SEMI-ANNUAL EVENT 2010



FIGURE

7