


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NMB 1115432886

OPERATOR

Initial Report Final Report

Name of Company	Arapahoe Oil Field Services <i>244197</i>	Contact	Sergio Rameriz
Address	P.O. Box 1127, Hobbs, NM 88241	Telephone No.	(575) 390-7325
Facility Name	Remuda Basin 31-1	Facility Type	Well

Surface Owner:	State and Federal	Mineral Owner:	State and Federal	API No.	30-015-28137
----------------	-------------------	----------------	-------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	31	23S	30E	1980	North	1980	West	Eddy

Latitude N 32.25373350° **Longitude** W 103.92984150°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	120 bbl	Volume Recovered	None
Source of Release	Transport Truck	Date and Hour of Occurrence	7/3/10 8:00 am	Date and Hour of Discovery	7/3/10 8:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, OCD, Artesia		
By Whom?	Bradley Blevins, Chesapeake Oil	Date and Hour	7/3/10 10:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Arapahoe truck was hauling water from Chesapeake Pierce Canyon well and spilled it's load At the Remuda Basin 31-1 site. No liquid was recovered.

Describe Area Affected and Cleanup Action Taken.* An area approximately 100' x 100' was affected from the spill. Soil samples were taken at surface and one foot depths to determine impact. The site will be remediated to OCD standards by Ocotillo Environmental. A final report and C141 will be submitted following remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Sergio Rameriz	Approved by District Supervisor Signed By <i>Mike Bratcher</i>		
Title: Manager	Approval Date: <i>8/25/2010</i>	Expiration Date:	
E-mail Address: daishaathome@yahoo.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/23/10 Phone: (575) 390-7325	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>9/25/2010</u>		

* Attach Additional Sheets If Necessary

FMLB 1115432582

2RP-793

Bratcher, Mike, EMNRD

From: Cindy Crain [cindy.crain@gmail.com]
Sent: Monday, August 09, 2010 11:12 PM
To: Bratcher, Mike, EMNRD
Subject: Initial C141, Arapahoe Oil Field Services, Remuda Basin 31-1
Attachments: Initial C141 Ramuda Basin.docx

Mike,

Attached please find the initial C141 for the Arapahoe Oil Field Services, Remuda Basin 31-1 produced water spill.

The Site is located in Unit Letter F, Section 31, T23S, R30E, Eddy County, New Mexico.

If you have any questions or need additional information please let me know.

Thank you,
Cindy Crain
(575) 441-7244

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Arapahoe Oil Field Services	Contact	Sergio Rameriz
Address	P.O. Box 1127, Hobbs, NM 88241	Telephone No.	(575) 390-7325
Facility Name	Remuda Basin 31-1	Facility Type	Well

Surface Owner:	State and Federal	Mineral Owner:	State and Federal	API No.	30-015-28137
----------------	-------------------	----------------	-------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	31	23S	30E	1980	North	1980	West	Eddy

Latitude N 32.25373350° Longitude W 103.92984150°


NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	120 bbl	Volume Recovered	None
Source of Release	Transport Truck	Date and Hour of Occurrence	7/3/10 8:00 am	Date and Hour of Discovery	7/3/10 8:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, OCD, Artesia			
By Whom?	Bradley Blevins, Chesapeake Oil	Date and Hour	7/3/10 10:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
Describe Cause of Problem and Remedial Action Taken.* Arapahoe truck was hauling water from Chesapeake Pierce Canyon well and spilled it's load At the Remuda Basin 31-1 site. No liquid was recovered.

Describe Area Affected and Cleanup Action Taken.* An area approximately 100' x 100' was affected from the spill. Soil samples were taken at surface and one foot depths to determine impact. The site will be remediated to OCD standards by Ocotillo Environmental. A final report and C141 will be submitted following remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Sergio Rameriz	Approved by District Supervisor:		
Title: Manager	Approval Date:	Expiration Date:	
E-mail Address: daishaathome@yahoo.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/23/10	Phone: (575) 390-7325		

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Yoni Strange [yoni.strange@gmail.com]
Sent: Wednesday, May 18, 2011 1:41 PM
To: Bratcher, Mike, EMNRD
Subject: Form C-141
Attachments: C-141_Chesapeake[1].pdf

Mike:

Pursuant to our conversation, attached is Form C-141. If you have any questions, please let me know.

Thanks,

Yoni Bolton
575/408-3671