

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Southwest Royalties INC	API Number 3.0-0.15-04626
Property Name North Hackberry Yates Unit	Well No. 110

Surface Location									
UL - Lot J	Section 24	Township 19S	Range 30E		Feet from 1650	NS Line S	Feet from 2310	EAV Line E	County EDDY

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJECTOR NO	SWD	OIL	PRODUCER GAS	DATE 6-23-2020	

OBSERVED DATA

	(A) Surface	(B) Interval (1)	(C) Interval (2)	(D) Prod Comp	(E) Tubing
Pressure	0			0	25
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	C02
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Is used for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test not witnessed

Dan D. Molk

Compliance officer

9-4-2020

Signature: <i>M. Y. Merchant</i>	OIL CONSERVATION DIVISION
Printed name: M. Y. Merchant	Entered into RBDMS
Title: Production Supervisor	Re-test
E-mail Address: mymerchant@penrocoill.com	
Date: 6-24-2020	Phone: 575-492-1236
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM