

## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

1964 APR 23 AM 10:25

Name of Company

Southern Union Production Company

Address

P. O. Box 808 - Farmington, N.M.

Lease

Tijeras Canyon Unit

Well No.

2

Unit Letter

E

Section

12

Township

10 North

Range

5 East

Date Work Performed

4/9/64

Pool

County

Bernalillo

THIS IS A REPORT OF: (Check appropriate block)

☐ Beginning Drilling Operations☐ Casing Test and Cement Job☒ Other (Explain):☒ Plugging☐ Remedial Work

Plugging Back to Dakota Formation

Detailed account of work done, nature and quantity of materials used, and results obtained.

1. Drilled 7-7/8" hole to T.D. of 2179 ft. R.K.B. with mud.
2. Spotted cement plug from 1813 ft. to 1600 ft. with 100 cu. ft. of 4% gel. with 2% C.C. and plug from 1493 to 1275 with 150 cu. ft. w/2% C.C. Intervals between plugs was filled with 9.4#/gal. Drilling mud. Job complete 8:30 P.M., 4/9/64.
3. Suspend operations to evaluate prospect.

Witnessed by

Richard Paterson

Position

Tool Pusher

Company

S. S. Reames Well Service

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

## ORIGINAL WELL DATA

D F Elev.

T D

P B T D

Producing Interval

Completion Date

Tubing Diameter

Tubing Depth

Oil String Diameter

Oil String Depth

Perforated Interval(s)

Open Hole Interval

Producing Formation(s)

## RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by

Title

Date

Name

D. G. Macy

Position

Petroleum Engineer

Company

Southern Union Production Company