

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NY 013710
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

MAY 31 1963

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 1-B is located 2344 ft. from N line and 1885 ft. from W line of sec. 26.
SE 1/4 NW 1/4 (1/4 Sec. and Sec. No.) 7 N (Twp.) 4 W (Range) N.M.P.M. (Meridian)
Wildcat (Field) Valencia (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6042 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well has surface marker cemented. No knowledge of plugging procedure.
Report made for record purposes only. Bond to be cancelled; lessee to be held responsible for any future damage for improper plugging of well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Gore & Lipson Oil Prop.

Address 812 Sims Bldg.

Albuquerque, New Mexico

(Orig. Sgd.) P. T. McGRATH

By P. T. McGrath

U.S.G.S.

Title District Engineer, Farmington