

	X		

(SUBMIT IN TRIPLICATE)

MAIN OFFICE UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1958 JUL 21 AM 9

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Santa Fe, New Mexico

Land Office _____
Lease No. **NM 013710**
Unit _____

RECEIVED
JUL 18 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 7th, 19 58

FEDERAL

Well No. **1-B** is located **2344** ft. from **N** line and **1855** ft. from **E** line of sec. **28**

SE of NW of Sec. 26 **7 North** **4 West** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

WILDCAT **Valencia** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6042** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Ran 134' of 8 5/8" -J- 55 - 28#/ 100 Sx

Ran wire line - 10' fill up, then pressured up/ 1 hour

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **GORE & LIPSON OIL PROP.**

Address **812 SUMMIT Bldg.**

Albuquerque, New Mexico

By **Byron Gore**
BYRON GORE
Title **Partner**