Budget	Bureau	No.	42-R359	1.4
Approv	al expire	× 12	-31-A0	

(Feb. 1	951)	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office
Lease No. 039087
Unit

SUNDRY NOTICES AND REPORTS ON WELLS MAR 9 19

NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY		SURVEY MEXICO
(INDICATE ABOVE BY CHECK MARK	(NATURE OF REPORT, NOTICE, OR OTHER DATA) March 4	i \$ 0	

				, 9 _U
Well No. 1-14 is located	ted 1650 ft.	from ${N \choose 2}$ line	e and 990 ft. from $\left\{egin{array}{c} \mathbf{E} \\ \mathbf{W} \end{array} ight\}$ line	of sec. <u>14</u>
NE/4 of Sec. 14	6-N	11-W	NMPM	
(1/2 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Wildcat	Valend	cia	New Mex	100
(Field)	(Co	ounty or Subdivision)	(State or Territo	
The elements of the 1 11	0 1	, , ,	_	

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well is being drilled with cable tools. The casing program to 3-1-60 has been:

- 13-3/8" 48# H-40 casing set at 390' w/cement circulated - 10-3/4" 40.5# casing set at 1374' - mudded off.
- 8-5/8" 24# J casing being "carried" at 2404'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Southland Royalty Company Address Box 1515 Midland, Texas