



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. N. M. 032087

Unit _____

RECEIVED

MAY 16 1960

SUNDRY NOTICES AND REPORTS ON WELLS

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 12, 1960

Well No. 1-14 is located 1650 ft. from N line and 990 ft. from E line of sec. _____

NE 1/4 sec. 14 6 N 11 W N.M.P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Valencia New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD of well is 4638'. Spotted cement plug from 4200' to 4300'. Pulled
→ 1635' of 8-5/8" cas. Pulled 740' of 10-3/4" csg. 13-3/8" pipe set at
390', (cement circulated) still in hole. Spotted 15 sack cement plug
in top of 13-3/8" csg. Capped casing - left 4' pipe marker extending
up from well head. This well plugged per instructions of Mr. McGrath
with USGS

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SOUTHLAND ROYALTY CO.

Address P. O. Box 1515

Midland, Texas

By /S/ Alton C. Goodrich

Title District Production Supt.