

RECEIVED

MAR 27 1972

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator ODESSA NATURAL CORPORATION	8. Farm or Lease Name Odessa Natural Corp. W S Ranch
3. Address of Operator P. O. Box 3908, Odessa, Texas 79760	9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> <u>1275</u> FEET FROM THE <u>West</u> LINE AND <u>2446</u> FEET FROM THE <u>South</u> LINE, SECTION <u>30</u> TOWNSHIP <u>30N</u> RANGE <u>20E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR 7057', KB 7070'	12. County Colfax

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Temporarily Abandoned</u> <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

March 23, 1972 TD 4965'

Drilling operations on this well were suspended this a.m. because of mechanical difficulties. Two fish were left in hole:

1st Fish	1 Bit (7-7/8" OD) Bit sub, 18 - 6" OD Drill Collars	543'
	13 Joints of 4" FH DP	402'
2nd Fish	18 Joints of 4" FH DP	552'

Bottom of first fish is @ 4965'. Top first fish is @ 3984'
Bottom of second fish is @ 3919'. Top second fish is @ 3362'

Well will be shut-in temporarily.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John J. Strojek</u>	TITLE <u>MANAGER - PRODUCTION</u>	DATE <u>3/23/72</u>
JOHN J. STROJEK		
SIGNED BY <u>J. E. Tipton</u>	TITLE <u>Oil & Gas Inspector</u>	DATE <u>4/10/72</u>
COPIES OF APPROVAL, IF ANY:	<u>Dist IV</u>	
5/NMOCC-Santa Fe, 1/WSRanch, 1/RIH, 1/Rowman, 1/LIS, 1/WF110		